



Daily Operating Checklist

- ✓ Preheat afterburner and confirm required temperature
- ✓ Make sure air intake areas are free of obstructions
- ✓ Keep combustibles away from unit
- ✓ Weigh charges and record weight before charging
- ✓ Stay within recommended maximum charge weight
- ✓ Cremate animals with high fat content or highly combustible containers early in the day
- ✓ Let unit cool in between charges
- ✓ Keep plastics down to a minimum, 5% of total charge weight max, incidental to body bag, **NO TRASH**
- ✓ Check for opacity/smoke, especially with large charges or those with high fat content
- ✓ Make sure printed daily record shows date and time of each charge



Routine Maintenance Checklist

Weekly

- ✓ clean opacity sensor lens (if equipped) and calibrate equipment

Monthly

- ✓ clean spark plugs and set gaps
- ✓ clean flame detectors (if equipped)

Quarterly

- ✓ check primary chamber and refractory for wear
- ✓ inspect exterior condition of exhaust stack
- ✓ check the combustion chamber jacket for VISUAL SIGNS of hot spots (be careful!)

Twice yearly

- ✓ check condition/clean draft fan

(NOTE: These maintenance checkpoints are provided for your general information, always verify maintenance needs and recommended time schedules with your equipment manufacturer)